

**To:** Bill Simon[wsimon@frontier.net]; Peter Butler[butlerpeter2@gmail.com]; Steve Fearn[fearneng@rmi.net]; Allen Sorrenson - DNR[allen.sorensen@state.co.us]; Way, Steven[way.steven@epa.gov]  
**Cc:** Steven Renner - DNR[steven.renner@state.co.us]  
**From:** Brown - DNR, Kirstin  
**Sent:** Mon 4/14/2014 9:16:55 PM  
**Subject:** Gold King and Sunnyside Workings and Drill Holes Map  
[GoldKing\\_Sunnyside\\_DrillHoles.pdf](#)

Here is a map showing the Gold King workings and Sunnyside Workings, including drill holes. The drill information has no dip azimuth information. So, I measured everything in plan view along a horizontal plane. So essentially this is worst case scenario. The actual distance between Gold King 7 and the drill hole are almost surely farther.

Let me know if you have any more questions.

Distance = 370 feet to Sunnyside drill hole from Gold King 7

--

Kirstin Brown  
Colorado Division of Reclamation, Mining and Safety  
691 C.R. 233, Suite A-2  
Durango, CO 81301  
(970) 903-7889  
[kirstin.brown@state.co.us](mailto:kirstin.brown@state.co.us)